QC2- Inspect parts off machine FAI/FAIB

0.00

QC

Quality Control

Memo

0.00

B11-7-13

120

QC8- Inspect parts - second check

Quality Control

Memo

	. Johnson								
W/O:			WC	ORK ORDER CHANGE	ES				
DATE	STEP	PRO	CEDURE CHA	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				, , , , , , , , , , , , , , , , , , , ,					
									<u> </u>
Part No	:	PAR #:	Fault Cate	gory:	NCR: Yes	No DQ	A :	Date:	
		esolution:							
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)	•		
DATE	DATE STEP Description of NC			Corrective Action Section		Verific	eation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date		ction C Chief E		QC Inspector
					_				



Page 2

Tuesday, July 12	2, 2011 0.37	. JJ AWI											
Item ID:	D3442-1			Acc	ept					Setup	Start		
Revision ID: Item Name:	Shim										Stop		
Start Date: Required Date: Reference:	7/12/2011	Start Qty: 12.00 Req'd Qty: 12.00	_			Cust Item 1 Customer:	ID:						11 0 11 0 1101 1001
Approvals:	Process Pla	an:	Date:	Te	ooling:	D:	ate:			Run	Start		
			Date:		PC (Y/N):		ate:				Stop		
Sequence ID/ Work Center II)	Operation Description			Set Up/ Run Hours	Teol ID	Tool #	Plan Code	Accept Qty	Reje Qty		Reject Number	Insp. Stamp
130 Small Fab		Small Fab			0.00						 -		
Small Fab		Deburr if nec	essary.										
. 140 QC Quality Control		QC5- Inspect part comple Memo	eteness to step		0.00	S							
			/	. 10	0	10			_				

0.00

Packaging

Packaging

150

Identify as per dwg & Stock Location

Memo *****STOCK IN BASKET CELL**** SHU 11-07-20

	•								
W/O:			WO	RK ORDER CHAN	GES				
DATE	STEP	PRO	OCEDURE CHAI	NGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						<u> </u>			
Part No	:	PAR #:	Fault Cate	jory:	NCR: Yes	No DQ	A:	Date: _	
	R	esolution:	Disposition	1:	QA: N/C C	losed:	***************************************	Date: _	
NCR:			WORK ORDE	ER NON-CONFORM	IANCE (NCI	R)			
DATE	STEP	Description of NC Section A	Initial	Corrective Action Se Action Description	ection B Sign	0 1	cation	Approval Chief Eng	Approval QC inspector
		OCCIIOTA	Chief Eng	Chief Eng	Date	360		Officer Errig	QC IIIspector
									į
									-
ı				•				,	

Work	0	rder	ID	71	783
VVUIN		ıucı	117	/ 1	7 (0.3

Tuesday, July 12, 2011 8:57:35 AM



Page 3

Item ID:

D3442-1

Accept

Tool # Plan

Code

Setup Start

Stop

Revision ID:

Start Date:

Item Name:

Required Date: 7/18/2011

Shim

7/12/2011

Start Qty: 12.00

Req'd Qty: 12.00



Date:

Cust Item ID:

Customer:

Tool ID

Reference:

A	nn	ro	va	le٠
-	บข	U	٧a.	15.

QC:

Process Plan:

Operation

Description

Date:

QC21- Final Inspection - Work Order Release

Tooling:

Date:

Date:

Start Stop

Qty

Run

Accept

Qty

Reject Reject Insp.

Number

Sequence ID/ Work Center ID

160

QC

Quality Control

Memo

Run Hours

0.00

SPC (Y/N):

Set Up/

0.00

Stamp

W/O:			W	ORK ORDER CHANGES	3			· · · · · · · · · · · · · · · · · · ·	
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				•					
Part No	•	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQ	A:	Date: _	
	Re	esolution:	Disposit	ion:	QA: N/C C	losed:		Date:	
NCR:			WORK OR	DER NON-CONFORMAN	CE (NCF	R)			-
DATE	STEP	Description of NC	91 S.A.,	Corrective Action Section I		Verific	ation	Approval	Approval
DAIE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign of Date	🛂 Secti		Chief Eng	QC Inspector
					·				1
	٠,								

Picklist Print

Tuesday, July 12, 2011 8:57:47 AM

Work Order ID: 71783

Parent Item: D3442-1

Parent Item Name: Shim



Start Date: 7/12/2011

Required Date: 7/18/2011

Start Qty: 12.00

Required Qty: 12.00

Comments:

IPP A□05.09.02□New issue□KJ/JLM□

Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	Primary Location	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Qty per Kit	Total Qty	Qty Issued	Date Issued	Status
M304S22GA		Purchased	No			100	sf	139.3600	0.04	0.505263	١.		
	 	•								Bil	-7-13	3	

304/316 .032 Sheet

<u>Location</u>	Loc Qty	Loc Code	
020	5.8		
109057	5.8		
MAT020	133.56		
117379	37.56		117374
118271	96		



W/O: DATE STEP	PR	WO	RK ORDER CHAN					Approval	
DATE STEP	PR	OCEDURE CHAN	IGE					Annroval	
				В	У	Date	Qty	Chief Eng / Prod Mgr	Approval QC Inspector
		·				,			
		,		·					
Part No:	PAR #:	Fault Categ	jory:	NCR: `	res N	o DQ /	4 :	Date:	
Resol	lution:	Disposition	ı:	QA: N/	C Clos	ed:		Date: _	
NCR:		WORK ORDE	R NON-CONFORM	IANCE (I	ICR)				
DATE STEP	Description of NC			ction B			ation		Approval
DAIL GIL	Section A	Initial Chief Eng	Action Description Chief Eng		ign & Date	Section	on C	Chief Eng	QC Inspector
				-					
				·					
						•			


D3065-5DART AEROSPACE LTD	Work Order:	71783
Description: Shim	Part Number:	D3442-1
Inspection Dwg: D3442 Rev: A		Page 1 of 1

	FIR	ST ARTICLE I	NSPECTI	ON CHI	ECKLIST		
		X First Art	icle	Prot	otype		
Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Con	nments
1.750	+/-0.010	1.742	>		V 1302		
2.500	+/-0.010	2,491	b		V		
0.750	+/-0.010	744	r		V	-	
0.034	+/-0.010	150,	2		V		
0.750	+/-0.010	,742	2		V		
		<u>.</u>					
<u> </u>							
			-				
			-				
leasured by:	1B	Audited by:			Prototype Ap	proval:	N/A
	., 7 2	Data	 U		.,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,,	Doto	NI/A

Measured by: (B	Audited by:	Prototype Approval:	N/A
Date: ((-7 - 13	Date: 1107/13	Date:	N/A

Rev	Date	Change	Revised by	Approved
Α	07.07.18	New Issue	KJ/JLM A	E
			——————————————————————————————————————	

W/O:			W	ORK ORDER CHANG	ES				
DATE	STEP	PROCEDURE CHANGE				Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC inspector
	-								
Part No:		PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQ	A:	_ Date: _	
	R	esolution:	Dispositio	on:	_ QA: N/C CI	osed:		Date:	
NCR:		V	VORK ORD	ER NON-CONFORM	ANCE (NCF	R)			
DATE	STEP	Description of NC Section A		ion B	Verific	cation	Approval	Approval	
			Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Secti	on C	Chief Eng	QC Inspector
		,			; 				
								-	



W/O:		WORK ORDER CHANGES										
DATE	STEP	PR	OCEDURE CH	CEDURE CHANGE			Date (Qty (Approval Chief Eng / Prod Mgr	Approval QC Inspector		
	9				1							
Part No	•	PAR #:		tegory:		R: Yes I	No DQA:		Date:			
Resolution:		esolution:	Disposition:			: N/C Cld	sed:		Date:			
NCR:			WORK OR	DER NON-CONF	ORMANCE	(NCR)					
DATE	STEP	Description of NC Section A	Initial Chief Eng	Corrective Action Action Description Chief Eng		Sign &	Verificat Section		Approval Chief Eng	Approval QC Inspector		
		;	Offiel Eng	Office Eng		Date				,		
		, i							·			
									ļ			
	L						İ					